

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 1 INVESTIGATION OF
OPERABLE UNIT 3-06
11/04/94**

FILE NUMBER

AR1.7 INITIAL ASSESSMENTS

▲ Document #: 5397
 Title: CPP-33, Contaminated Soil in the Tank Farm Area Near WL-102, NE of CPP-604, OU
 3-06
 Author: N/A
 Recipient: N/A
 Date: 10/14/86

▲ Document #: 5398
 Title: CPP-34, Soil Storage Area in the NE Corner of the CPP, OU 3-06
 Author: N/A
 Recipient: N/A
 Date: 10/14/86

▲ Document #: 5404
 Title: CPP-40, Lime Pit at the Base of the CPP-601 Berm and French Drain,
 OU 3-06
 Author: N/A
 Recipient: N/A
 Date: 07/08/87

▲ Document #: 5411
 Title: CPP-47, Pilot Plant Storage Area West of CPP-620 Plant West of
 CPP-663, OU 3-06
 Author: N/A
 Recipient: N/A
 Date: 10/15/86

AR3.5 TRACK 1 INVESTIGATIONS

▲ Document #: 5198
 Title: CPP-47 Pilot Plant Storage Area West of CPP-620 Plant West of
 CPP-663
 Author: N/A
 Recipient: N/A
 Date: 09/14/92

▲ Document #: 5304
 Title: CPP-33 Contaminated Soil in the Tank Farm Area Near WL-102, NE of CPP-604
 Author: N/A
 Recipient: N/A
 Date: 06/24/93

**IDAHO NATIONAL ENGINEERING AND ENVIRONMENTAL LABORATORY
ADMINISTRATIVE RECORD FILE INDEX FOR THE TRACK 1 INVESTIGATION OF
OPERABLE UNIT 3-06
11/04/94**

FILE NUMBER

AR3.5 TRACK 1 INVESTIGATIONS (continued)

▲ Document #: 5732
 Title: **CPP-40** Lime Pit at the Base of the CPP-601 Berm and French Drain
 Author: N/A
 Recipient: N/A
 Date: 06/07/94

▲ Document #: 5756
 Title: **CPP-34** Soil Storage Area in the NE Corner of ICPP
 Author: N/A
 Recipient: N/A
 Date: 06/27/94

NOTE: Sampling data can be examined at the Technical Support Building, 1580 Sawtelle.